

From: ["Wallingford, Jonni B." <wallingfordjb@cdmsmith.com>](mailto:wallingfordjb@cdmsmith.com)
To: ["Sheldrake, Sean" <sheldrake.sean@epa.gov>](mailto:sheldrake.sean@epa.gov)
["Zhen, Davis" <Zhen.Davis@epa.gov>](mailto:Zhen.Davis@epa.gov)
CC: younghs@cdmsmith.com
["Scott Coffey" <coffeyse@cdmsmith.com>](mailto:coffeyse@cdmsmith.com)
Date: 8/6/2018 12:45:34 PM
Subject: Subsurface Coring /sheen
Attachments: [image002.jpg](#)
[image003.jpg](#)
[image004.jpg](#)
[ATT00001.txt](#)

Good Afternoon,

Included are photos of SC-S117 /RM 6.5, coring attempt #2. The Pre-RD group has observed and recorded sheen in the river after coring attempt #2. NRC took action by applying sheen booms around the SMA, containing the product. Additionally, the Pre-RD group has observed and recorded that the core contains NAPL (photo 4).

Photo 1: core attempt #2
[Image]

Photo 3: Pre-RD group observes sheen presence in surface after core extraction

Photo 3: NRC applies boom pads

Photo 4: Pre-RD has recorded, and classified core #2 as containing NAPL

Get Outlook for Android<<https://aka.ms/ghei36>>